



UM11
Socketschaltungen
UCH42, UAF42, UL41

| Schalter | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 |
|----------|---|---|---|---|---|---|---|---|---|----|----|----|----|----|----|----|----|----|
| TA | | | | | | | | | | | | | | | | | | |
| U | | | | | | | | | | | | | | | | | | |
| K | | | | | | | | | | | | | | | | | | |
| M | | | | | | | | | | | | | | | | | | |
| L | | | | | | | | | | | | | | | | | | |

Messinstrument: 1 kΩ/V
(300V- bzw. 30V-Bereich)

~ 105V