


ECH81

EBF80

Attention

EBF80


EL84



CORDEREAUX	RESISTANCES
C1	1000 PF
C2	250 PF
C3	0.1 MF
C4	100 PF
C5	500 PF
C6	5000 PF
C7	50000 PF
C8	200 PF
C9	10000 PF
C10	25000 PF
C11	8 MF 350V
C12	2x50MF350V
C13	100 MF 25V
C14	1000 PF
C15	10000 PF 1000V

RESISTANCES	WATTAGE
R1	50 KA
R2	200 KA
R3	30 KA
R4	30 KA
R5	1 MA
R6	1 MA
R7	100 KA
R8	1000 KA
R9	500 KA
R10	50 KA
R11	240 KA
R12	10 KA
R13	750 KA

TRIMMERS: Orl. P.O.  
 O.C. P.O.  
 O.C. G.O.  
 O.C. O.C.



CORRES CONVERTES	POINTS D'AGREMENT
O.C.	14.7 - 5.68 MC
P.O.	1400 - 574 KC
G.O.	500 - 750 KC
Ferrite P.O.	900 KC
Ferrite G.O.	150 KC

Transformateur 856 A

6 LAMPES NOVAL

AVEC ANTENNE FERRITE

SOCORA