



Condensateurs	Résistances
C1 1000 PF	R1R12 50 K Ω
C2 250 PF	R2 200 Ω
C3C9 0,1 MF	R3 30 K Ω
C4 100 PF	R4 30 K Ω
C5C22 500 PF	R5R6R7 1 M Ω
C6 C7C8 50000 PF	R9R11 1 M Ω
C8C19 50000 PF	R8 100 K Ω
C10C12 200 PF	R10 1000 Ω
C11 10000 PF	R13R22 500 K Ω
C13C16 25000 PF	R14 30 Ω
C17 8 MF 350 v	R15 2000 Ω
C18 2x50 MF 350 v	R16R17 100 K Ω
C20 100 MF 25 v	R18 10 M Ω
C14 1000 PF	R19 1 M Ω
C21 10000 PF 1000 v	R20 50 K Ω
	R21 240 K Ω
	R23 10 K Ω
	R24 150 Ω

1/4 W 1 W 2 W 3 W

Couverts	Point d'alignement
O.C. 16.7 - 5.88 MCS	15 MCS
P.O. 1620 - 510 KCS	1400 - 574 KCS
G.O. 300 - 150 KCS	200 KCS
Ferrite P.O.	900 KCS
Ferrite G.O.	150 KCS

6 LAMPES NOVAL
AVEC ANTENNE FERRITE

SOCORA